

construction engineering research laboratory



INTERIM REPORT M-254 August 1978 Corrosion Abatement Design Criteria

EFFECTS OF CORROSION ON MILITARY FACILITIES OF THE PRESIDIO OF SAN FRANCISCO

INC FILE COFY

by Christopher Hahin





The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED
DO NOT RETURN IT TO THE ORIGINATOR

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION		BEFORE COMPLETING FORM
CERL-IR-M-254	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
EFFECTS OF CORROSION ON MILITARY OF THE PRESIDIO OF SAN FRANCISCO	INTERIM 5. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(*) Christopher/Hahin		8. CONTRACT OR GRANT NUMBER(*)
9. PERFORMING ORGANIZATION NAME AND ADDRESS CONSTRUCTION ENGINEERING RESEARCH P.O. Box 4005 Champaign, IL 61820	LABORATOR:	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 4A762731AT41+T7-001
11. CONTROLLING OFFICE NAME AND ADDRESS	/	August 1978 / / / / / / / / / / / / / / / / / / /
14. MONITORING AGENCY NAME & ADDRESS(II differen	t from Controlling Office)	15. SECURITY CLASS. (of this report) Unclassified 15. DECLASSIFICATION DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abatract entered	in Block 20, if different from	m Report)
18. SUPPLEMENTARY NOTES Copies are obtainable from National Springs	al Technical Info field, VA 22151	ormation Service
19. KEY WORDS (Continue on reverse elde II necessary an atmospheric corrosion military facilities facility life cycle costs	d identify by block number)	
The effects of atmospheric of Presidio of San Francisco induced Problem areas include deteriorate hardware, refrigeration and air of electrical distribution lines. Fration rates are made, along with als 5-551K and 5-680C. An informengineers (Corps of Engineers Dis	corrosion on milid by airborne salion of galvanized conditioning complecommendations to suggested revise mation exchange m	t fall are described. I sheet metal, building conents, and exterior to decrease deterio- sions to Technical Manu- nechanism between design

DD 1 JAN 73 1473

EDITION OF THOU 65 IS OBSOLETE

SECURITY CERSSIFICATION OF THIS PAGE	(When Pate Briefed)
Block 20 continued.	
(Facility Engineers) to measures to decrease 1 ities, are also recommo	o improve facility longevity is proposed. Other ife-cycle costs, consistent with military prior-ended.
The second secon	


UNCLASSIFIED

FOREWORD

This investigation was performed for the Directorate of Military Construction, Office of the Chief of Engineers (OCE), under Project 4A762731AT41, "Design, Construction, and Operations and Maintenance Technology for Military Facilities"; Task 7, "Materials for Military Construction"; Work Unit 001, "Corrosion Abatement Design Criteria." The applicable QCR is 1.03.007, "Parametrics of Corrosion." The OCE Technical Monitor is Mr. E. Hunt.

The study was performed by the Engineering and Materials Division (Dr. G. R. Williamson, Chief), U.S. Army Construction Engineering Research Laboratory (CERL).

 $\,$ Dr. L. R. Shaffer is Technical Director of CERL, and COL J. E. Hays is Commander and Director.



CONTENTS

	DD FORM 1473 FOREWORD	1 3
1	INTRODUCTION Background Objective Approach Mode of Technology Transfer	5
2	ANALYSIS OF FINDINGS	7
ر	FACILITY LIFE-CYCLE MAINTAINABILITY	15
4	CONCLUSIONS	17
5	RECOMMENDATIONS	18
	APPENDIX A: Recommended Changes to TM 5-551K APPENDIX B: Recommended Changes to TM 5-680C	19 26

EFFECTS OF CORROSION ON MILITARY
FACILITIES OF THE PRESIDIO OF SAN FRANCISCO

1 INTRODUCTION

Background

Corrosion results in a significant drain on the Army's real property resources. A study of Army and Air Force installations has indicated that 8 to 24 percent of real property maintenance expenditures are corrosion related, depending on local topography and climate. Since corrosion rates are usually quite low, problems often appear long after the facility is built. Corrosion-induced failures may be caused by (1) improper design for the particular environment, (2) use of low-cost, but high corrosion rate materials, or (3) lack of normal preventive maintenance.

This report is part of an overall study of corrosion-related problems on military installations in various climatic zones in North and South America. The Facility Engineer organization and the Area Resident Engineer organizations are being analyzed to determine predominant corrosion problem areas, and to recommend research where the state of the art is inadequate. Changes to Technical Manuals (TMs) or Guide Specifications are recommended when necessary.

Objective

The purpose of this part of the study was to analyze the deterioration of facilities and subcomponents in a temperate seacoast environment. System components having either favorable or unfavorable performance in this environment were specifically noted as being indicators of superior (and usually cost effective) or inferior construction over the long run. Maintenance or operational procedures which could increase facility life at less cost were also investigated.

¹ C. Hahin, Corresion Costs of Air Force and Army Pacilities and Construction of a Cost Prediction Model, Technical Report 77-17 (Air Force Civil Engineering Center, 1977).

Approach

The Presidio of San Francisco was selected as the study site for this environment. Supervisors of major work sections engaged in corrosion-related work were interviewed. Key engineers were contacted about maintenance and repair actions, including those accomplished inhouse or by construction contract. Deteriorated components were examined, and corroded facilities and equipment were inspected. Corrosion problems were later analyzed to determine if existing technology or Army procedures could remedy the difficulty.

Mode of Technology Transfer

Results of this study impact on TM 5-551K (AF TO 40P-1-131), Flumbing and Pipefitting, and TM 5-680C, Overhead Pictribution Systems. (Recommended changes to these manuals appear in Appendices A and B, respectively.) Other TMs and Guide Specifications which may be affected are TM 5-810-1, Heating, Ventilation and Air Conditioning; TM 5-670, Heirigeration, Air Conditioning, Mechanical Ventilation and Evaporative Cooling, TM 5-625, Sheet Metal; TM 5-805, Builder's Hardware; TM 5-810-5, Plumbing; CE 251.01, Builder's Hardware; CE 301.36, Central Fefriacration System; and CE 303.7, Aerial Flectrical Distribution.

2 ANALYSIS OF FINDINGS

Economic Impact of Corrosion at the Presidio

The Annual Work Plan of the Presidio served as a basis for discussion with first-line supervisors about how their workers spent maintenance time. Each supervisor was asked to describe the nature of his segment of the Work Plan, and to estimate the percentage of each repair, maintenance, or replacement action that was related to metallic corrosion. Each job was evaluated by the following criteria:

- 1. Was the failure or deterioration of a metallic component corrosion-induced?
- 2. Did corrosion of a component result in damage to the building or its contents?
 - 3. Was scale removed or scaled-up equipment replaced?
- 4. Was preventive maintenance, such as boiler water treatment or cathodic protection, performed to reduce corrosion losses?

Construction contracts from FY70 through FY75 were evaluated by the same criteria. Most of the corrosion-related work is confined to maintenance and repair contracts. Only one Military Construction-Army (MCA) project during the 6 year period analyzed was corrosion-related; a sewer replacement project for \$209,600.

An analysis of the Annual Work Plan revealed that plumbers, sheet metal workers, heating mechanics, and exterior electricians spend a substantial amount of time on corrosion-related jobs. In terms of the Presidio's total operating budget (excluding Camp Parks and Troop Units), about 10.5 percent of all Facility Engineer expenses are related to corrosion. Similarly, about 8.9 percent of all construction contracts (non-MCA) stem from corrosion problems. Tables 1 and 2 contain a more detailed summary of these results.

Corrosion Effects on Systems and Components and Recommended Solutions

Plumbing Systems

Deterioration of underground piping at the Presidio was caused by fairly low soil resistivity (ranges from 1,500 to 6,700 ohm-cm) and long burial times. Fixture replacement was confined to chrome-plated brass spouts and various zinc die-cast handles. The brass alloys failed because of general load-bearing section reduction caused by selective

Table 1 Summary of Facility Engineer Corrosion Costs for the Presidio

Work Section	% Corrosion- Related Work	Corrosion Cost ^b (\$)	Total Operating Costb (\$)
Plumbing	55.7	196,649	353,124
Refrigeration	20.3	41,210	400,106
Heating Systems	22.5	59,273	264,000
Boiler Plant	23.1	53,432	230,912
Interior Electric	9.3	30,144	325,000
Exterior Electric	22.4	51,296	229,000
Water Plant	12.2	26,039	214,060
Woodworking	12.6	59,184	468,000
Metalworking	33.5	41,850	125,000
Painting	*	-	155,000
Roads and Pavements	0.9	3,510	390,000
Engineering Services	8.9**	56,797	638 175
Preventive Maintenance	10 (est)	19,000	190,000
Hospital Support	4 (est)	12,579	314,496
Other Sections and	-	-	1,923,090
Supervisory Overhead		650,963	6,219,963

Overall Corrosion % = 10.5

^aExcludes Camp Parks and Troop Units b Includes labor, equipment, and materials, FY77 dollars

^{*}All wood and masonry structures
**Derived from 6-year maintenance and repair project averages

Table 2

Corrosion-Related Project Totals (non-MCA)
for the Presidio of San Francisco

Fiscal Year	Total Contract \$ Volume	Corrosion-Related Value
70	1,840,759	268,146
adjusted for inflation*	2,959,320	431,088
71	1,436,105	84,755
adjusted for inflation*	2,085,085	123,056
72	1,926,862	150,936
adjusted for inflation*	2,444,109	191,453
73	1,230,133	159,058
adjusted for inflation*	1,428,234	184,672
74	1,139,478	162,602
adjusted for inflation*	1,231,011	175,663
75	3,076,278	72,882
Totals (adjusted)	13,224,037	1,178,814

Overall average: 8.9%

^{*}Adjusted by comparing Engineering News-Record Construction Cost Indexes for respective years, using FY 75 (December) as a baseline. Costs are multiplied by ratio of FY 75 index to fiscal year index in question.

leaching of zinc. Zinc die-cast handles failed either from galvanic action with the brass or steel valve stem, or by intergranular attack. These failures can be abated by prohibiting zinc and beta-brass components in applications which require superior longevity. Coppers, high copper alloys, or red brasses should be used for areas experiencing dealloying of zinc.

Copper and galvanized steel were used for all aboveground pressurized piping. Although plastic piping is corrosion resistant to most waters, its use was restricted to underground waste distribution systems. Reasons cited for not using plastic pipe aboveground were (1) brittleness caused by its exposure to sunlight, (2) the nigh coefficient of expansion, and (3) insufficient durability during a fire. Plastics used in underground piping were acrylonitrile-butadiene styrene (ABS) and polyvinyl chloride (PVC). Personnel were concerned about the shelf life and long setting times of ABS adhesives, and ABS piping had reportedly been chewed through by rats. PVC pipe had not been penetrated.

The Repairs and Utilities TM 5-551K, **Reading and **Repairs** by, was not used as a primary source of technical direction for maintenance actions. Rather, a "national" code was used, although several codes claim universal status. TM 5-810-5 requires that initial system design comply with the **Iniform Flumbing** Design of the International Association of Plumbing and Mechanical Officials, but TM 551K does not specify a national code for maintenance actions. The national codes should be referenced in TM 5-551K and supervisory personnel directed to obtain copies (at Government expense) of the prevalent code in their region. These "national" codes usually are more progressive than local codes and allow use of more modern materials, since they are revised annually.

Exterior Chest Metal Work

Galvanized steel roofing was not extensively used throughout the installation. Because roofing is either clay tile or built-up asphalt layers on a wood base, deterioration of exterior sheet metal was confined to guttering. Aluminum gutters developed pits caused by accumulated salt fall, and plastic gutters degraded after prolonged exposure to sunlight. Many of the plastic gutters cracked when ladders were

3 Propolard Plumbing to be (Southern Building Code Congress International,

4 1976).

**Mrimer Thereford Filmining Vol. (National Association of Planting Matrices Continue Contin

² Teliform Flording Cale (International Association of Plumbing and Mechanical Officials, 1976).

Plumbing-Heating-Cooling Contractors, 1976).

5 Bord Brain Flumbing Toda (Building Officials and Code Administrators International, 1976).

placed against them, presenting a safety hazard. The galvanized guttering, whether original or replaced, was not specified with any minimal zinc thickness.* The ASTM AS25 G90 Commercial Zinc Coating class should be used as a minimum (0.90 oz/sq ft [275 g/m²]) requirement. Hot-dipping of formed sheets with zinc coatings ranging from 1.15 to 2.3% oz/sq ft (351 to 717 g/m²) in the triple-spot test may be necessary for areas experiencing severe degradation, since forming sheets will cause flaking of the thick zinc coatings. The base metal should be a copper bearing steel, 0.2 percent copper minimum.

Another problem involving metal work was the constant need to replace galvanized vent stacks. Because these vents are exposed to heated furnace exhaust gases, they have an average life span of 5 to 8 years in the salty air. A superior metal for long-life applications would be commercially pure titanium in the fully annealed condition for formability. Unlike the thin gauge galvanized steel, the titanium would resist both the oxidative effects of heated gases and chloride attack. For vent stacks requiring shorter life with less chloride exposure, TT-P-38 Ready-Mixed Aluminum Paint applied to galvanized steel is suitable for temperatures up to 300°F (149°C). For temperatures beyond 300°F (149°C), TT-P-28 Heat Resisting Aluminum Paint is indicated.

Bur Ming Eurobrane

The use of zinc-chromated steel lock hardware or an unchromated varnished steel causes a major problem at this location. Typical life of this hardware is 5 to 8 years. A similar situation exists for steel butt hinges exposed to salt air. Door closers also have a reduced life, caused mainly by internal moisture accumulation. An all-brass lock has a typical life span of 16 years at the Presidio. However, many of the so-called "all-brass" locks (passage, dead bolt, anti-jimmy) supplied by the General Services Administration (GSA) contained steel parts, especially where strength was a requisite. This can be a worse situation than one in which the components are all-steel because the manufacturer has substituted steel for critically-stressed parts. Steel corrodes at

and the second second

^{*} NOTE: CE 220.08, <u>General Sheet Metalwork</u>, does not permit selection of galvanized gutters. For "corrosion locations," this specification selects copper or copper-clad stainless. However, the copper-clad stainless is so thin (0.015 in. [.33]0 mm]) that any discontinuities in the thin copper cladding would lead to severe pitting where salt fall occurred, such as at the Presidio.

⁶ ASTM Standard A525-75, Annual Book of Standards (Part 3) American Society for Testing and Materials (1976)
7 F. LaQue, "Corrosion Testing," Proceedings of ASSM, Vol 51 (1951), pp. 495-582.

1 to 2 mpy (0.025-0.05 mm/yr) compared with 0.021 mpy $(5.25 \times 10^{-4} \text{ mm/yr})$ for cartridge brass, ^{e,9} not taking galvanic action into account.

Refrigeration-Related Components

Aluminum framing for dust filtration of intake air was badly pitted, and in several cases, completely corroded through. Dust filters accumulate the salt-laden air, and eventual evaporation concentrates the salt, resulting in a very saline dew. When a new hospital complex suffered framing failure after only 2 years, Facility Engineer personnel attempted to replace the framing with austenitic stainless steel, but evidently received a ferritic or martensitic grade (personnel stated the material was magnetic). This is an example of material substitution granted by nontechnical purchasing agents. In this location, a copper-nickel alloy (67 percent Ni, 33 percent Cu) would probably sustain less pitting in creviced areas than stainless steel.

Difficulties were also reported with rapid deterioration of aluminum evaporator and condenser fins, especially when coupled to copper tubing. "Spine" fins were also severely degraded. In general, these fins could not be brushed and should be prohibited in saline exposures. All-copper fins and tubing are mandatory for this location.

Flectrical Distribution Systems

The principal difficulty at this site was the high resistance caused by corrosion at aluminum conductor drop lines which lead to the main circuit-breaker panel. The aluminum service drop at the weather head apparently accumulates moisture and overheats because of section loss or shorts. Neither the manufacturer of the weather head nor the type of wire insulation is known.

Another difficulty was caused by the failure to install ground rods when cast iron water mains were replaced with plastic. This left the seemingly grounded cold water pipe in a state where current may not drain away, depending on soil moisture conditions and the depth of the steel-plastic joint.

⁸ H. Copson, "Long-Time Atmospheric Corrosion Tests on Low-Alloy Steel," *Proceedings of ASCM*, Vol 60 (1960), pp 650-665.

⁹ C. Hummer, C. Southwell, and A. Alexander, "Corrosion of Metals in Tropical Environments -- Copper and Wrought Copper Alloys," Materials in trotection, Vol 7, No. 1 (1968), pp 41-47.

Electrical Listribution Systems, Exterior

The principal corrosion problems in these systems are corrosion of aluminum conductor/steel-reinforced (ACSR) and copper conductor splices and the deterioration of transformer cases.

Electricians at the Presidio use two types of connectors to join aluminum to copper. In the first method, a compression connector (with conductive grease) joins the aluminum to a copper pigtail, which then connects with a split bolt joining the copper cable. Split bolts are never retightened because of the danger of exceeding the flow stress where relaxation will occur; rather, they are simply replaced. The second connector is a wedge-shaped compression device which joins the cables by explosive force, requiring a powder-actuated tool. Its superiority in this environment may stem from permanent seizing induced by friction heating and extremely high compressive stresses at points of sliding impact. (See Figure 1 for details on this connector.) The use of compression-type splices in humid and saline areas should be emphasized in TM 5-680C. However, various proprietary connectors must be compared in several humid locations under monitored conditions of amperage, temperature, and dew point, before any particular connector can be endorsed.

Transformer cases require frequent repainting because of salt air and dew accumulation. In several instances, actual penetration through the case occurred. Since it is difficult to completely remove products without reducing case thickness, an economical coating system would be TT-P-615 Basic Lead Silico Chromate Primer Coating, Type I (0il) or Type V (0il & Alkyd), with a TT-E-522 Lustreless Phenolic Enamel, which has good resistance in humid seacoast areas. For extremely corrosive locations, use of MIL-P-38336 Inorganic Zinc Dust Primer and MIL-C-38427 Urethane or Epoxy Top Coating is indicated, although this coating system requires more careful surface preparation.

When Hystems

Leakage of raw water from heat exchangers was thought to contaminate boiler condensate. Conductivity should be tested periodically to determine if such a condition exists. Conductivity monitoring might be considered for new construction at key system locations. Inability to treat the water for low pressure boilers was also reported, as was damage to sodium silico fluoride injectors used for fluoridation of






Figure 1. Powder-actuated compression-type fastener. Heat generated from friction, combined with mechanical seizing, may account for reported longevity of this connector. Conductive grease is also used.

drinking water. A suggested alloy for these injectors is Monel 200* (67 percent nickel, 31.5 percent copper, 1.25 percent iron), which has good resistance to any hydrofluoric acid (HF) which may form. 10 Another alternative is AISI 316, which has good resistance to hydrofluosilicic acid (H $_2\mathrm{S}_1\mathrm{F}_6$), although pitting may develop. 11

^{* &}quot;Monel 200" is a proprietary alloy manufactured by Huntington Alloys. Monel indicates a 67 percent Ni 33 percent Cu nominal composition. In addition, The American Water Works permits Hastelloy, rubber linings and several inert plastics like Teflon and polyethylene (F. Maier, "Fluorides in Water," Water Analogy & Treatment, McGraw Hill, 1971).

¹¹ R. Swandby, "Nickel Base Alloys," *Corrosion Resistance of Metals and Alloys*, ASC Monograph 158 (Reinhold, 1963), pp 522-524.
C. Paul and J. Moran, "Stainless Steel," *Corrosion Resistance of Metals and Alloys*, ASC Monograph 158 (Reinhold, 1963), pp 393-394.

3 FACILITY LIFE-CYCLE MAINTAINABILITY

Certain organizational impediments to effective corrosion control found at the Presidio were also typical of problems encountered at other Army installations.

Maintainability of Construction

The District Engineer is responsible for the timely completion of a Military Construction project, keeping a close watch on cost growth, whereas the Facility Engineer is more concerned with maintainability. These goals may not necessarily be convergent. A continual, positive interplay must exist between the District and Facility Engineers so that new construction does not repeat the errors of the past. Both shortand long-term information regarding facility maintainability problems discovered after acceptance can significantly contribute toward improved construction. Long-term feedback is particularly important since corrosion problems often surface many years after the facility has been in use.

Both the Army and the Air Force have various <code>short-term</code> construction deficiency reporting mechanisms, but there is no <code>life-cycle</code> deficiency reporting system at present. A life-cycle reporting system proposed by the Directorate of Facilities Engineering (DAEN-FEM), OCE, suggests that recommendations for facility improvements be forwarded to major commands rather than the District. 12 However, corrosion is a region-specific phenomenon, and therefore is better controlled through on-going dialogue between the District and Facility Engineers. This dialogue could be accomplished by having the Facility Engineer submit an annual consolidated installation summary of facility maintainability trends (regardless of facility age) to the District, with information copies to OCE and major commands.

The advantages of a regional life-cycle reporting system are multiple, especially for corrosion problems. A regional system avoids universal adoption of specific materials, products, or procedures (minimizes manufacturer endorsement problems). A cost comparison of alternate materials could be taken into account, since prices vary depending on source of manufacture and shipping rates. Historical precedents for specification of a successful material would be provided for a particular region, and would be grounds for rejection of other materials because of their documented failure in certain applications.

¹²DAEN-FEM message dated 012106Z Dec 76; Subj: Interim Change, AR 420-10: Construction Improvement Recommendation.

Material Substitutions and Intended Facility Life

The superior material for a given application is one that has sufficient corrosion resistance which complements its mechanical or other required properties. However, other materials may be substituted during procurement, especially when acquisition price is the determining factor, and not the corrosion rate or long-term cost. This is particularly applicable to bench stock replacement items which are not subject to rigid material specifications. Although the lot-priced item seems equivalent and apparently less expensive, over the long run these components may have to be replaced several times, involving installation and procurement costs. Since corrosion rates vary with location, determining the cost effectiveness of replacement component parts may take several years. This can be accomplished by noting demand levels for various items over the years, or studying specific high replacement items in designated buildings, and noting differences in lifetimes of parts of generic equivalence.

Inferior materials are often used on buildings and structures which are kept long beyond their intended lifetime. In many cases, there is no rigid disposal schedule. If intended facility life is short, there is reluctance to use a superior material. This attitude persists because of the advanced physical age of many Army facilities. However, if labor force levels are reduced in the future, components must have a longer life since personnel may not be available to replace the shorter-life component.

4 CONCLUSIONS

- 1. The Facility Engineer of the Presidio allocates about 10.5 percent of his resources to corrosion-related work, including preventive maintenance, repair, and replacement actions.
- 2. Approximately 8.9 percent of all non-MCA Presidio maintenance and repair contracts are the result of corrosion. This percentage was obtained by adjusting prior year corrosion costs for inflation, adding them, and then dividing by total adjusted maintenance and repair contract values for the 6-year period analyzed.
- 3. Underground piping and potable water distribution systems incurred substantial losses. Atmospheric deterioration of exterior metal components was due to airborne salt fall.
- 4. Dealloying of thin-wall brass fixtures and failures of zinc die cast handles were common occurrences.
- 5. Although galvanized steel was used extensively, no attention was paid to zinc coating thickness specification.
- 6. Coated steel locks and hinges required frequent replacement because of corrosion. This problem was compounded by the inability to obtain the required all-brass components from GSA.
- 7. Aluminum condenser and evaporator fins deteriorated rapidly, decreasing heat transfer efficiency. Pitting, crevicing, and generalized attack occurred, especially with aluminum fins on copper tubing.
- 8. The corrosion of aluminum conductors joined to copper caused difficulties for electricians.
- 9. Formal mechanisms to provide feedback between the design agency and the inheriting maintenance organization on long-term corrosion-related deficiencies do not exist.

5 RECOMMENDATIONS

- 1. Closer controls should be placed on stocking the proper replacement parts for specific buildings, especially considering intended lifetime. It is not recommended that the best alloy always be used, but rather that a superior alloy or material be designated only for buildings that will require long-term service. This implies stocking multiple types of a generic item.
- 2. It is recommended that life-cycle cost rather than initial cost be considered. The life-cycle cost can be roughly indicated by watching demand levels on specific replacement parts over a period of years.
- 3. A facility deficiency reporting system which feeds long-term system life information back to the District from the Facility Engineer should be considered for adoption. This will permit formal dialogue between construction and maintenance forces, and will provide the District with design information regarding facility maintainability.
- 4. Several sections of TM 5-551K (AF TO 40P-1-1-31) and TM 5-680C should be revised in accordance with the recommended changes listed in Appendices A and B.

APPENDIX A:

RECOMMENDED CHANGES TO TM 5-551K

Page 1 of 6

										Page I (
		D CHANG BLAN	K FOR	MS			Special To	Elisis	o for Repai - Kristello	of Supply	29 Jun 1977	
TO: 150 Commar US Arn	dant y Engir	rel Center. priment of pictures. Reer Schi , VA 221	001	n or formi	Incluse Z	IP Code;	County Supply No. 2018 No. 2017					
PUBLICA	ATION-FOR	PART	I - ALI	L PUBLI	CATIONS	DATE	T RPSTL AF	TITLE		ANK FORMS		
TM 5-9	51K (A	TO 40P	-1-13	1)		July	1971	Plum	sbing and	l Pipefit	ting	
ITEM NO.	PAGE NO.	PARA- GRAPH	LINE NO.	FIGURE NO.	TABLE NO.		(Ехвс			HANGES AND orded change or		
2.	4-1	4-1a(1) 4-18	6			handliron press stain cost iron marke pared alkal due t alloy steel Add: and f cript	ing acidi should be ure, use less stee analysis pipe are d corrosi to gray ier well, o caustic s and hig s will to Place as lange uni ion: "*A	c corrused monells." and prade cast exception retails on cast teris on c	rrosives, d. For solor nick pEASON: provision, high si esistance iron. I per tor solor te high color aption.	high sitting care leading to repulsion care to stroke twill history and join Add to Fe with die	igure 4-18 des- electric gaskets	
3.	4-16	4-23b	3			Add: Place asterisks on ground joint union castio and flange union caption. Add to Figure 4-18 description: "*Also available with dielectric gasket and bolt sleeves for coupling dissimilar metals; similarly, dielectric ground joint unions are also manufactured." REASON: Availability of this fitting variation should be made known to decrease galvanic corrosion of pipe junctions in corrosive media. Delete "will not rust, not or corrode." Insert "is not corroded by most natural and treated waters. Some plastics are susceptible to degradation by certain strong acids, organic solvents and sunlight. They are also subject to embrittlement at freezing temperatures." REASON: Statement is too general and misleading to the uninformed reade						
CHRIST	OPHER +	DE OR TITL IAHIN allurgis	.ε	lerence t	TELEPH PLUS EX	like not b blems will	netäls, a e thought	re er of a are c corro	subpurses	nt-sensit e-all for inces whe	astics. Plastic ive and should corrosion pro- re plastics	

DA FORM 2028

RECOMMENDED CHANGES TO PUBLICATION BLANK FORMS				AND Use Pair Distriction of the Laptic Parts and Special 4 of the OFFST Count September 2009			SATI			
	of this form jutant Gene	, see AR 310 rol Center.	}-1, me:	teencqoic	agency is	the US	Catalogo os			
TO: (+ 0	www.ard.topro	ponent of pu	iti lec #1100	i ur formi	Include 2	(r. Conte)	FROM. 100	ليده در در	s e an e i propere d'un see	
(con	TINUATI	0N)								
PUBLIC	ATION FOR		1 - AL	L PUBLI	CATIONS	TEXCEP	T RPSIL A*	io sc	MEAND BLANK FORMS	
l		F TO 40F	2-1-10	31)		luly	1971		rbing and Pipefitt	149
ITEM	PAGE	PARA-	LINE	FIGURE	TABLE			RECCA	UMENDE: JHANGES AND PI	FATON
NO.	NO.	GRAPH	NO.	NO.	NO.	2 1 /			potre in over mit change en a	
4.	10-4				10-4	ŀ			ole 10-4: "Water cond in copper pip	
						resul	t in inte	rnal	erosian carrosian	damage."
5.	12-3	12-5c	10						n buried sections protection applied	
			ĺ			areas	may requ	ire w	ire jumpers to mai	ntain continu-
						coupl		tue	higher resistance	uresser
6.	10-8,	10-8				REASO	N: This	paraq	raph requires comp	olete revision.
, . 	10-9					Severa	al corros	ion r	echanisms are inco orms of corrosion	ompletely ex-
						encour	nter (tes	ides	galvanic and gener	al attack) are
									re are more ways c two methods listed	
						4			rrosion on the bas onductivity is con	
						vanic	differen	ces u	sualiv stem from :	innerent metal-
						films	. For ex	ample	rmation of adherer , titanium nas pod	or IACS con-
				ļ					far superior perfo fair electrical co	
						descr	iption of	corr	osion as a replati the dealloying of	ing process in
						nost (cases the	iron	forms an insolubl	le corrosion
]									ntent.pH, and vel Impressed-current	
									r alloy section ar oned as additional	
				Ì		ne tho	ds. SUGG	ESTED	REVISION: "a. (Corrosion is
İ						envir	onment.	Plumb	a material or allo ers replace large	quantities of
									resion, especially ter supply piping.	
									are encountered by ack, which results	
	<u></u>			<u> </u>	<u> </u>	of pi	oe walls.			
TYPED	NAME, GRA	DE OR TIT		elecence :			Thin the para- HANGE AGT		SIGNATURE	
					PLUSE	A E #510#	•			
					}				•	

DA . FORM. 2028

RECOMMENDED CHANGES TO PUBLI BLANK FORMS							Special T	1 Lists	tor Requir Parts and VPSTL: and Supply	CATE
For use of Army Adjut			-1, the p	roponent o	igency is i	he US	Catalings ():	gyiv Mi	nuals (31) NM.	
TO: (Family	ard to proj	onent of pu	th at-	i z turmy!	1 /на≠ Z	(P C S≠)	FROM: /A //	victor wind	Lwatten : ,nctode ZIF 1 odes	
(CONT)	INUATIO	OM)								
PART I - ALL PUBLICATIONS							T RPSTL AN	DSC 5	MI AND BLANK FORMS	
PUBLICAT	ION FOR	R 38MUN N				DATE		THILE		
TM 5-55	51K (A	TO 40	P-1-1.	31)		July	1971	Flu:	bing and Pipefitt	ing
ITEM NO.	PAGE NO	PARA- GRAPH	NO '	FIGURE NO	TABLE		Exact		MENDED CHANGES AND RE of recommended change must	
NO.	NO	GRAPH	No ·	NO	ON	attacerosi lar c when acidi highl mostl metal sever metal by a of ea vanic serie	other fok, (2) pion corrosion 1) The uthe amounty incready acidic, y in undready acidic, y in undready acidic, and it is behave an joint galvanic corrosions for communicative metal active metal activ	rms of ting ion, and (niform tof (see inkab nic a ed by e cova will son the mon potals	f corrosion are (1, (3) crevice corrosion (5) dealloying, (6) stress corrosion of stepsygen, the temper Since most potable less than 4 would le process water. Ittack occurs when threads or flanger rosion depends on ter or soils. How last can be roughles. The greater the series, the more I take place. A relumbing alloys is Gold, silver Titanium Stainless steel Nickel alloys Bronzes Copper and bras Tin Lead Cast iron Mild steel Aluminum alloys Cadmium Zinc Magnesium dielectric fitting	galvanic cosion, (4) intergrand in el increases ature, and trace water is not be found two different is. The how the two volumes are predicted in separation likely galough galvanic as follows: s (austenitic)
			• <i>R</i> ,	teren e t	o hee nu		i <u>ng mater</u> 'n de sind		tichpuragraph.	
TYPED NA	ME, GRAC	JE OR TITE					HINGE AUTO		SIGNATURE	

DA . FORM . 2028

REPLACES DA FORME 124 1 DEC 64 WHICH WILL BE USE

Page 4 of 6

RECOMMENDED CHANGES TO PUBLIC BLANK FORMS	ATIONS AND	CATE Constant II in server for Repure Parts and
For use of this form, see AR 310-1, the proponent a Army Adjutant General Center.	gency is the US	Special In Costs Rinding and only Catalogs Supply Manuals (SC SM)
TO: Esward to proponent of put lication within a	In take Zir C + e ;	FROM A 15 I varia (warrant in orde ZIP Code)
(CCMTINUATION)		
PART I - ALL FUBLIC	ATIONS EXCEP	PT PETL AND SC SWIAND BLANK FORMS
PUBLICATION FORM NUMBER	DATE	TITLE
TM 5-551K (AF TO 40P-1-131)	July	/ 1971 Plumbing and Pipefitting
TEM PAGE PARA- LINE FISHER NO NO. GRAPH NOT NO	TABLE NO.	PEODMYFNEED CHAN IFS AND REASON (Exact Anding of recommended Change must be given)
	in a corrotende or by Stain to pi chang mater (in the cause place water (porolly we moist (of the metal is he tible stop to reelimin be ne (usual alloy coppe iron (grap of br the p will	(3) Pittin: ucrum: when corrosion takes place is small area, and the surnounding area is not reded. This may be caused by the inherent lency of the alloy to bit in certain corrosions, by contaminants that may settle, inducing pits, nless steels, magnetium, aluminum and zinc tend bit. Since it is usually more difficult to age environment, it is best to substitute a reial that does not pit. (4) Crevice corrosion occurs when conditions the piping system are not uniform, usually led by the pining design. Gaskets are common ses where oxygen is partially excluded, but may not. Gaskets with a wicking action rous) often suffer crevice corrosion. Improperteded seams which do not completely seal out of ture are also susceptible. (5) Erosion corrosion occurs when the velocity of the water exceeds a certain critical value. The clean of the complete its protective film because it reing swept away. Copper is especially suscepte to erosion corrosion. Recommended ways to the gully-like attack of erosion corrosion are educe pressure, increase pipe diameter or sinate sharp bends. Substitution of steel may necessary. (6) Dealloying is a form of corrosion that is ally found in brass or cast iron. In brass lys, the zinc leaches out leaving a weak spongy er (dezincification). For gray cast iron, the offerrite) corrodes out, leaving just graphite phitization). To prevent dezincification, use prasses with nore than 70, copper should reduce problem. Neither ductile nor malleable iron suffer graphitization like gray cast iron.
TYPED NAME, GRADE OR TITLE	TELEPHONE FR. PLUS EXTENSION	C. IT IE AUTOLIN, SIGNATURE ON
D4 5084 0000		

DA .: 2028

Parle & get 5

RECO)AQAENDI	ED CHARC BLAN	ES TO		CATION	S AND	Luc Part 1	Consistence Conference professional Conference Conference professional Conference Confer					
	nt this form Jurant Gene	, see AP 3"' eral Center.	^; mes	troponent.	agence of		\$ 1 . S	Age of March 1990 Marc					
10- 17	•w≉rd to pr	ctionant of pi	it to mean	i ar Engini i	et i trasa Z	11 (FF3M 4	tie van troatras projete 2183 ole.					
(6)	HIGUATI	ON)											
B. O. G				. FUBLI	CATIONS	EXCER EATE	TAPITLA	ABY WARDE, ANT FORUS					
POBLICATION COMMINGER IM 5-5516 (AF TO 46P-1-131)						l	1071						
ITEM	PAGE	PARA.	T	FP,URE	TARLE	1.1.11.	13/1	Ply Time and Paperisting Hermanness Here takes					
МО	NO	GRAPH	N 7 1		40.			Education Franciscope of Pauge Contract Con	·· —-				
						corro	sion res	io, tile and malleatle from his a solutione similar to that of steek.					
						(7) Interpresular corrector is solutions encountered by ply bors. In die cast functional handles or sixl duain solutions for but the fill corrode this way, becoming mittle. The elimpion alloys are susceptible. Therefore element the microscopic metal crystals corate medials, causing eventual rupture, in users or the recall are preferable alloys for such cases.							
			(8) Stress corresion is rarely encountered by plumbers, and is usually a problem in non-potable water or other process problem in non-sure. Stress corrosion marking included to the action of a specific corresive on certain the when piping is under pressure. An example is assured bring contained by stainless stall the resurrized bring contained by stainless stall the resurrized brass in contact with anaponia. Not all notices behave the same when subject to pressurized corrosives; some are morn resistant than there. Stress-corrosion chacking takes class family quickly, from several days to a few years, or sult with engineering personnel if you are stall this form of corrosion to be a problem.										
						(9) Several methods are available at the plumber's discretion to solve corrosion in thems. He may change the material during replacement of the piping to one more suited for the environment. He may alter the configuration (but not interfering with operation) to increasing the corrector or changing bend revenity. If excessive air is being drawn into the sy tem, he may evolude if or recommend that the pH be changed at its source, in drinking water is involved, changes must not one any detrimental effects on public health. Pripage							
1 485.		L OE OR TITI		terence r				de chine i tape traph					
, 1060	MAME, SH/	IDE ON TIT	i E.		PLUSE	HUNE E FI. X TENSION	redictions.	JA H. SIGNATURE					

DA . FORM. 2028

HEPLACES DA FORM 2748 IL DEC 48 MILICH WILL HE USE

Page 6 of 6

RECOMMENDED CHANGES TO PUBLICATION BLANK FORMS For use of this form, see AR 316-1, the propunent agency is							See and Tee	treverse) for Ropair Parts and Uponto PESTIO and Surply	CAY
	of this form divising Gener		el, me;	propunent	agency is i	me US		up, Iv Mansatts →C 5M)	
10: . + .	ward to pr	spanent of pu	r loates	n or trem)	din lude 7	In some	FROM: Acti	ist y word to minori) to lode ZIP C do	•,
(604	H INUATIO	DM)							
<u> </u>				L PUBLI	CATIONS	· — · — ·	T RPSTL AN	ID SC SMI AND BLANK FORMS	
ł	ATION FOR					CATE		1.766	
<u> </u>		F TO 400		·	·	duly	1971	Plumbing and Pipefit	
NC:	PAGE NC	FARA- SHAPH	-INE NO	FFIGHF NO	TAHLE	ļ +	Exect	HECCHMENDED CHAN IES AND E twisting of recommunitid change in	
7	10-9 A-1	10-8c(3				teflo burie tion ment the ozinc (rect mains (corro and M (MR), Anoth neer: Add: report unbrocorro Add n Codes Assoc Los A Code. Birmi Finch Heati Encin Code, Inter	on, or zired, he sho is being of magnes operation packaged Lifier) cas and late (10) For osion, see dilitary S. Composition, by For which we paragration of the cosion by the cosion by the cosion by the cosion of	more detailed informate TM 5-811-4, Cornocial Standardization Handboom and Cornocian Pacter general reference is Contana and Greene." scaling in a water mater plant personner is beneficial and preforming a protective library of Plumbing and Mechanical Building Code Congresions test ediction. Scaling Mational Association of Contractors, Washing atest ediction. BCCA Fig Officials and Code Adjusted Code Adj	lines that are thedic protectes the replace-eaters, and maynesium or-current tems on buried tion about the Controlok MIL-HDBK-/2levion of Metals. Empoten Empi-in should be nel. Thin events ayer." ized Plumbing rnational cal Officials, and Flumbing of Plumbing of Plumbing and Flumbing and Flumbing at Flum
TYPED	NAME, SRA	UE OR TITL		nterem e i	I TELEP	ONE EXC	+ MGE AUTO	Traph or schreedfragh TVON, ISIGNATURE	···
					Ρέψει	r TÉNSIÓN	1		

DA . 108M . 2028

PERLACES DA FORM 2028 I DEC 68 WHICH KILL HE USES

APPENDIX B:

RECOMMENDED CHANGES TO TM 5-680C

PRECEDING PACE NOT FILMED

RECOMMENDED CHANGES TO PUBLICATION BLANK FORMS						SAND	t east;	and the second second	DATE				
	of this form, Istant Gener	100 AR 310			agency is	the I'S	Special Do Carollini	Addison (Maria Displace of State of Sta	29 Jun 1977				
Comman US Arm	dant y Engin Jelvoir,	iger Sch	001	r og fren i	Ho fire Z	IP v · · ·	Us Arrov Construction Engineering Research calonatory Champaign, II elect						
		PART	I - ALI	. PUBLI	CATIONS	FICEP	T RESTL AN	SU JE JOHANE HEARK FORUS					
PUBLIC	ATION FOR	M NUMBER				DATE		T-7: (
TM S	5-63 0 C		,	y	·	Ser	p 63	Overhead Distribution	Systems				
ITEM NO.	PAGE NO.	PARA- GRAPH	LINE NO.	FIGURE NO.	TABLE NO.		(Exe.	RECOMMENCED CHANGES AND AS IN viting of recommended change mus					
1	47	31	16			Insert the following after" conditions." "Powder-actuated compression connectors which have comparable performance are also available (see Figure 56)." PEASON: Superior performance of the type of connector has been reported by field personnel. Such connectors perform markedly better than split bolts in humid or marine areas.							
2	47	31				Add new paragraph: "c. Compression connectors are recommended for splicing and tapping in humid or marine regions. It is critical that the junction, especially if aluminum is being connected, have sufficient anti-oxidant conductive grease to exclude moisture, dew, or salt accumulation. Many splices have prefilled grease containers which uniformly seal the junction upon compression, whereas others require the electrician to coat mating surfaces with antioxidant grease before tightening the joint."							
3	47			56		tightening the joint." Replace split bolt photograph with one of powder-actuated wedge connector. REASON: Since shape of split bolts is well known, the superior and less familiar connectors should be shown.							
TYPED	AME GRAC	GE OR TITE		Inters of t	TELESIE		a trat A: "	triph is subjected to phy. 1704: 15:54ATURE					
TYPED NAME, GRACE OR TITLE TELLES CHRISTOPHER HAHIN						CTE NOI 24	6511, Ext	101	itali.				

CERL DISTRIBUTION

Director of Facilities Engineering APO NY 09427

```
US Army Engineer Listenet
New Orleans
ATTN: Library
ATTN: Crief, LMN:0-DG
Ittle Polk
ATTN: Chief, Engines
    DARLOM STILL-EUR
  APO New tork 09710
 West Point, NY 10996
ATTN - Sept of Mechanics
ATTN - Litrary
                                                                                                                                                                                                                                                     Tulsa
ATTN: Library
Albuquerque
ATTN Library
CHIRALY

ATTN CARLADIO
ATTN CA
                                                                                                                                                                                                                                                       Alim Libro.
Pan Francisco
ATTN Chief, Empo 5.
                                                                                                                                                                                                                                                        acramento
ATTN Chief, Hikto
                                                                                                                                                                                                                                                       ATTN Chief, Oben
                                                                                                                                                                                                                                                       Heattle
Patth Heaf MPSON
                                                                                                                                                                                                                                                     Alin nie.
walla walia
Alin Libnary
Alin Chief, ingr Div
                                                                                                                                                                                                                                                    Alaska
ATTN Library
ATTN NPAGE-R
         Canadian Force Thatwon Officer (4)

U.S. Acc. Mod life Equipment

Reserver and Development Command

Et Bel. in, VA John
                                                                                                                                                                                                                                         U. Army Engineer Division
                                                                                                                                                                                                                                               / Army ingineer Division
Lurape
ATTN Technical Library
New England
ATTN: Library
ATTN: Chief, NEDED-T
North Atlantic
ATTN Chief, NADEN-T
South Atlantic
ATTN Chief, SADEN-T
ATTN: Library
Muntsyille
          Airports and Lougt Services Oir
Technical Information Reference
        featre
KAOL, Françoit Capada Bullding
Place de ville, Ottawa, Ontario
Canada, KIAONE
 Ft Belveir, VA 22060
ATTN - Kingman Bldg, Library
All Dr. Conflatjant
                                                                                                                                                                                                                                              ATIN: Library
Huntsville
ATIN: Library (2.
ATTN: Chief, HNDEG-SR
JOHN Hississippi Valley
ATIN. Library
Phio Piver
ATTN: Chief, Engr Div
North Central
ATIN: Library
Hissour' River
ATIN: Library
Hissour' River
ATTN: Library
Hissour' River
ATTN: Library (2)
Southwestern
Ft Monroe, VA 2-1653
ATTN: ATEN
ir McEmerson, GA 30530
ATTN: AFEN-FED
 NSA-WES
ATTN: Concrete Laboratory
ATTN Library
 6th USA
ATTN: AFFC+LG-E
                                                                                                                                                                                                                                                Southwestern
ATTN: Library
ATTN: Chief, SWDED-TM
 US Army Science & Technology Center
- Far East Office
                                                                                                                                                                                                                                               Pacific Ocean
ATTN Chief, Swood-m
ATTN, Chief, Engr Civ
North Pacific
ATTN Trief, Engr Div
  JS Army En ineer District
Buffalo
Affil Libiar,
Pitt-burgh
Affil Litrary
                                                                                                                                                                                                                                         Facilities Engineers
F1 Camphell, MY 42220
                                                                                                                                                                                                                                              Ef Campbell, VY 42221
JSAE(UM)
Ef Mommouth, VY 62703
JEAR, USAE()
Ef Benning, GA 11990
JEADOR
Ef Sick, VY 4170
Ef Sick, VY 4180
Ef, Sick Inf Sick, Ef Visio,
HC, Sick Inf Sick, Eff. Conf.
       Portadelphia
#ITN Library
ATTN Color, MAMENO
         Haltimore root, topolis.
Nortolk
         MOITN Chief, NAUFNOU
Willington
ATTN Chief, CAWEN B
     ATTY Chief, Tempa of
Charleston Chief, Engr (in-
Savanda)
ATTN Chief, "ANA" of
Backgongithe
ATTN Litery
ATTN Litery
ATTN Court Lize
Monate
                                                                                                                                                                                                                                       A: (ivi) Engr (enter/fR)
indal) AFB, F: 3,4-1
                                                                                                                                                                                                                                       Moval Air Systems Command
                                                                                                                                                                                                                                        A IN CABRALL
W/SH DC - 1765
        Mobile
ATTN: Chief, AMEN'S
ATTN: Chief, AMEN'S
                                                                                                                                                                                                                                       Nival Facilittes righ Command
ATTH (nde 04
A exandria, VA .2732
         Nashville
ATTN library
        Memphis
Afthr Chief, LMMED-DM
                                                                                                                                                                                                                                       Firt Hueneme, LA 93043
ATTN Library (Code 108A)
        ATTM: ....
Vicksburg
ATTM: Cnief, Engr Div
       ATTN: Chief, Engr Div
Louisville
ATTN: Chief, Engr Div
St Paul
ATTN: Chief, EG-D
                                                                                                                                                                                                                                      wishington, DC
AITN: Transportation Research Board
AITN: Library of Congress (2)
AITN: Dept of Transporation Library
        St Louis
ATTN: Library
Yansas City
ATTN. Library (2)
                                                                                                                                                                                                                                      limfense Documentation Center (12)
                                                                                                                                                                                                                                       Ingineering Societies Library
New York, NY 10017
         Omana
ATTN - Chief, Engr Div
```

```
Facility Engineers

AMC

Aberdeen Province Ground, Monotoph
Anny Materials and Monotoph
Sessarch Content, Monotoph
Sessarch Content, Monotoph
Burlington Anny Armunition Mant.

Ad UBD16

Corpus Christia Anny Econt, 17 78419
Frankford Content, No. 17763
Natick Committeers, MONOTOPh
Shape Anny English, MONOTOPh
Shape Anny English, MONOTOPh
COTE

United States Mulitary Asamely, Molo396

DWA
Anny Trolon His Section, BOLO315

FOSCOM
It Device, MA 01433
It Levis, WA 98433
It Levis, WA 98433
It Cord, Content
It Polk, 17 77459
Fresidio of an Francisco, CA 34129

MDW
English Content Monotoph Content
MMC

tavonse Molotoph Ground Content, NO. 17302

Uskland And Anders, CA 94376

Sunny Point Mulitary Ocean Terminal,
NO. 2011

PADDOC
Et molocoph, Content
Et Beng To represent IA Asolf
Et Beng To represent IA Asolf
Et Beng To represent IA Asolf
Et Boston, VA 2016

Et Monroo, VA 2016

Et Ritchie, HO. 27119

BSARSC

Kalter Food Frey Moderal Centen.
```

10 2007

Hahin, Christopher

Effects of corrosion on military facilities of the Presidio of San Francisco. -- Champaign, IL: Construction Engineering Research Laboratory; Springfield, VA: available from National Technical Information Service, 1978.

24 p.: ill.; 27 cm. (Interim report -- Construction Engineering Research Laboratory; M-254).

1. Corrosion and anti-corrosives. 2. Presidio of San Francisco, CA. I. Title. II. Series: U.S. Construction Engineering Research Laboratory. Interim report; M-254.